

Industrial Surface Renovator

BD 50 is a highly concentrated, water-soluble safety solvent. This formulation was developed for industrial applications where a safer, more powerful solvent is required. BD 50 penetrates, then emulsifies and lifts dirt, grease and grime from the application surface, leaving it completely renovated.

- ✓ **Penetrates, Dissolves and Emulsifies Industrial Grease, Oil and Dirt**
- ✓ **Attacks Molecular Structure That Bonds Soils to Surface**
- ✓ **Contains No Carbon Tetrachloride, Benzene, Kerosene, Naptha, Gasoline or Other Hazardous Solvents**
- ✓ **Completely Non-Flammable and Biodegradable**



...setting performance
standards worldwide...

APPLICATIONS

BD 50 removes a wide variety of soils and solves most problems associated with dirt, sludge and grime. The high dilution rate of BD 50 makes each application very economical.

Use BD 50 on industrial surfaces, machinery, floors and most painted surfaces. Automotive repair shops, fleet operators, aircraft maintenance centers and manufacturers have found this a highly versatile product for maintenance.

DIRECTIONS

The dilution chart below is a **general guide** in using BD 50. Each renovation situation depends on concentrations and types of soils present, which will affect the strength of dilution. A Poly V, Sure Shot or Trig Sprayer may be used for application. The product may also be applied by cloth, sponge or mop. Let the surface soak for 60 seconds and then rinse and wipe clean.

Use 20 parts water to 1 part BD 50 for:

Aluminum, Air Filters, Buses, Canopies Over Ovens, Conveyors, Distilleries, Exhaust Stains, Flues, Machinery, Ovens, Plastic, Stainless Steel, Swimming Pools, Trucks and Welding Equipment

Use 15 parts water to 1 part BD 50 for:

Acoustical Tiles, Light Fixtures, Porcelain, Refrigerators, Stoves and Wax Stripping

Use 10 parts water to 1 part BD 50 for:

Air Conditioning Units, Brick, Tile, Coal Mining Equipment, Greasy Concrete, Grills, Heavy Wax Buildup, Heater Blocks for Texturing Machines, Motor Shells, Whitewall Tires and Printing Presses

AUTOMATIC SCRUBBERS:

For general cleaning, use 25 parts water to 1 part **BD 50**. For stripping, use 15 parts water to 1 part **BD 50**. **Do Not Use Undiluted on Composition Floors, Water-Based-Painted Areas or Aluminum.**



...setting performance
standards worldwide...

C-9/PC-2115/0205